

TIME 11:00 AM
DATE 06/26/95
SUBTOTAL 7387 LB
TOTAL 7387 LB
WORLD RESOURCES CO.

9 PM

3.69 TONS
3

11:00 AM 06/26/95

WORLD RESOURCES COMPANY		No.
Load		Date <u>6-26-85</u>
Gross	<u>62 420</u>	From <u>ALASKAN COAST</u>
Tare	<u>58 800</u>	<u>1.91 TONS</u>
Net	<u>3,820</u>	<u>3 CF</u>
	lbs.	Weigher

received by

WORLD RESOURCES COMPANY

8113 WEST SHERMAN STREET / PHOENIX, ARIZONA 85043 / (602) 233-9166

JUN 28 1995


Mr. Gerald A. Thompson
Alaskan Copper Works
628 South Hanford Street
Seattle, Washington 98134

Dear Mr. Thompson:

Enclosed is the appropriate copy of the Uniform Hazardous Waste Manifest and the weigh ticket resulting from the transfer of the recyclable materials by your company to World Resources Company (WRC) and the transportation of these recyclable materials to the WRC Recycling Facility in Arizona for the purpose of recovering the metal values therein.

Sincerely,

WORLD RESOURCES COMPANY





Manifest Coordinator

Enclosures

Recycled Paper

AKC-0018183

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. WA 09 8 0 7 3 8 5 4 6 9 5 0 0 4		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
		3. Generator's Name and Mailing Address ALASKAN COPPER WORKS 3200 Sixth Avenue South Seattle WA 98134		6. US EPA ID Number CA 09 8 0 5 8 4 5 1 0		A. State Manifest Document Number		B. State Generator's ID	
4. Generator's Phone (206) 623-5801		5. Transporter 1 Company Name C.K.C., Incorporated		7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID 615014	
9. Designated Facility Name and Site Address World Resources Company 8113 West Sherman Street Phoenix, Arizona 85043		10. US EPA ID Number AZ 09 8 0 7 3 5 5 0 0		D. Transporter's Phone (408) 627-2595		E. State Transporter's ID		F. Transporter's Phone	
						G. State Facility's ID		H. Facility's Phone (602) 233-9166	
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)		12. Containers		13. Total Quantity		14. Unit Wt/Vol		1. Waste No.	
a. <input checked="" type="checkbox"/> RQ, Hazardous waste, solid, n.o.s., (D007), 9, NA3077		10/09 D M		072/00		P		D007	
b. <input checked="" type="checkbox"/> RQ, Hazardous waste, solid, N.O.S. (F006), 9, NA3077		06/03 CF		039/22		P		F006	
c.									
d.									
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above							
P.O.# M-42098									
15. Special Handling Instructions and Additional Information 24 HOUR EMERGENCY RESPONSE: 1-(800) 424-9300 CHEMTREC (USE CHEMTREC COMPANY CODE "WORR") WEAR GOGGLES AND GLOVES									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.									
Printed/Typed Name Gerald A. Thompson					Signature 			Month Day Year 06 19 95	
17. Transporter 1 Acknowledgement of Receipt of Materials					Signature 			Month Day Year 06 20 95	
18. Transporter 2 Acknowledgement of Receipt of Materials					Signature			Month Day Year	
19. Discrepancy Indication Space									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.					Signature 			Month Day Year 06 20 95	

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. WA 09807385465004		Manifest Document No. 65004		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.					
3. Generator's Name and Mailing Address ALASKAN COPPER WORKS 3200 Sixth Avenue South Seattle WA 98134						A. State Manifest Document Number							
4. Generator's Phone (206) 623-5801						B. State Generator's ID							
5. Transporter 1 Company Name C.K.C., Incorporated						C. State Transporter's ID 615014							
6. US EPA ID Number CA 0980584510						D. Transporter's Phone (408) 627-2595							
7. Transporter 2 Company Name						E. State Transporter's ID							
8. US EPA ID Number						F. Transporter's Phone							
9. Designated Facility Name and Site Address World Resources Company 8113 West Sherman Street Phoenix, Arizona 85043						G. State Facility's ID							
10. US EPA ID Number AZ 0980735500						H. Facility's Phone (602) 233-9166							
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers No. Type		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.	
a. <input checked="" type="checkbox"/> RQ, Hazardous waste, solid, N.O.S., (D007), 9, NA3077						2189 D M		2172/200		P		D007	
b. <input checked="" type="checkbox"/> RQ, Hazardous waste, solid, N.O.S., (D007), 9, NA3077						063 CT		039/212		P		F006	
c.													
d.													
16. Additional Descriptions for Materials Listed Above: See M-92098						17. Handling Codes for Wastes Listed Above							
15. Special Handling Instructions and Additional Information 24 HOUR EMERGENCY RESPONSE: 1-(800) 424-9300 CHEMTREC (USE CHEMTREC COMPANY CODE "WORR") WEAR GOGGLES AND GLOVES													
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.													
Printed/Typed Name Gerald A. Thompson						Signature 		Month Day Year 6 6 1 9 9 5					
17. Transporter 1 Acknowledgement of Receipt of Materials													
Printed/Typed Name Lloyd Hood						Signature 		Month Day Year 10 12 10 15					
18. Transporter 2 Acknowledgement of Receipt of Materials													
Printed/Typed Name						Signature		Month Day Year					
19. Discrepancy Indication Space													
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.													
Printed/Typed Name						Signature		Month Day Year					

MATERIAL IDENTIFICATION

1990
EMERGENCY
RESPONSE
GUIDE

DOT SHIPPING NAME: Hazardous Waste Solid N.O.S. (D007)
DOT HAZARD CLASS: Class 9
UN OR NA NUMBER: NA 3077

DOT EMERGENCY RESPONSE GUIDE 31

POTENTIAL HAZARDS

FIRE OR EXPLOSION

Some of these material may burn, but none of them ignites readily.

HEALTH HAZARDS

Contact may cause burns to skin and eyes.

Fire may produce irritating or poisonous gases.

Runoff from fire control or dilution water may cause pollution.

EMERGENCY ACTION

Keep unnecessary people away.

Isolate hazard area and deny entry.

Self-contained breathing apparatus (SCBA) and structural firefighters, s protective clothing will provide limited protection.

CALL CHEMTREC AT 1-800-424-9300 FOR EMERGENCY ASSISTANCE. (Use Chemtrec Company Code "WORR") If water pollution occurs, notify the appropriate authorities.

FIRE

Small Fires: Dry chemical, CO2, Halon, water spray or standard foam.

Large fires: Water spray, fog or standard foam is recommended.

Move container from fire area if you can do it without risk.

Do not scatter spilled material with high-pressure water streams.

Dike fire control water for later disposal.

SPILL OR LEAK

Stop leak if you can do it without risk.

Small Dry Spills: With clean shovel place material into clean, dry container and cover, move containers from spill area.

Small spill: Take up with sand or other noncombustible absorbent material and place into containers for disposal.

Large Spills: Dike far ahead of liquid spill for later disposal.

Cover powder spill with plastic sheet or tarp to minimizing spreading.

FIRST AID

In case of contact with material, immediately flush eyes with running water for at least 15 minutes.

Wash skin with soap and water.

Remove and isolate contaminated clothing and shoes at the site.

NOTE: If this response guide is used as an attachment for shipping documents, enter shipping manifest number in block below.

WAD980738546 95004

(Shipping Manifest Number)

NOTICE

TO: World Resource Company
8112 West Sherman Street
Phoenix, Arizona 85043

From: Alaskan Copper Works
628 South Hanford Street
Seattle, Washington 98134

SUBJECT: Land Disposal Restriction Notice

Manifest Number: 95004

Date of Shipment: 6-19-95

This shipment of material, which is being provided for recycling, is subject to the land disposal restrictions of 40 CFR, Part 268, Subpart D or the prohibitions specified in 268.32 or RCRA 3004(d). The applicable Land Disposal Restriction Information is provided in accordance with 40 CFR 268.7 and is shown below:

EPA Material Number	Regulated Constituent	Subcategory	Treatability Group	Treatment Standards	
				CFR Reference	Prohibition Level
D007	N/A	N/A	Nonwastewater	40 CFR 268.41 40 CFR 268.43	---

By: Gerald A. Thompson
Alaskan Copper Environmental Assistant

Material Safety Data Sheet

D007 Recyclable Material

Recycler's Facility Name and Site Address:

Issued: 3/18/94

World Resources Company

8113 West Sherman Street

Phoenix, Arizona 85043

Tel: 1-602-233-9166 Fax: 602-936-9164

Call CHEMTREC only in the event of emergencies during shipping that involve a spill, leak, fire, or accident (all calls are recorded)

For Emergencies During Shipping in the US or Canada, Day or Night, Call: **CHEMTREC 800-424-9300**
(Use CHEMTREC Company Code "WRR")
For calls from other countries call: 202-483-7616 Collect

Section 1

PRODUCT - MATERIAL IDENTIFICATION

Environmental Protection Agency (EPA) Waste Classification: D007

Generic Name: Chromium metal bearing sludge

Chemical Family: Non-Ferrous metal particulates

Synonym: Metallic Residues From High Frequency Burning Table

DOT Shipping Name: RQ, Hazardous Waste, Solid, n.o.s. (D007)

DOT Hazard Class: 9 ; Packing Group: III

DOT Identification Number: NA 3077

DOT Emergency Response Guide 31 Applies

Section 2

HAZARDOUS INGREDIENTS

Ingredient:	CAS Number:	Content %:	ACGIH-TLV	Toxicology:
Aluminum	7429-90-5	0-5	10 mg/m ³	No Data Available
Chromium	7440-47-3	0-15	0.5 mg/m ³	2.75 mg/kg (Rat, Oral)
Copper	7440-50-8	0-10	1.0 mg/m ³	0.35 mg/kg (Mouse, Oral)
Nickel	7440-02-0	0-10	1.0 mg/m ³	No Data Available
Zinc	7440-66-6	0-5	none established	No Data Available

Section 3

PHYSICAL AND REACTIVITY DATA

Description: Moist, Sandy consistency

Brown to Black colored

Water Content 10-20% by weight

Specific Gravity: 2.0 to 3.0

Solubility: Insoluble in water

Density: 100 to 150 lbs/cu/ft

Incompatible Reactivity: Extreme heat sources, Oxidants

Vapor Pressure: Insignificant

Stability: Avoid contact with acids, extreme heat

Polymerization: Will not occur

Boiling Point: Above 2000°C

Melting Point: Above 1000°C

pH: 7.0 to 10.0

Odor: Nil

Section 4

FIRE AND EXPLOSION DATA

Flashpoint: Nonflammable, under normal conditions

Oxidation: Non-oxidizing

Special Firefighting Procedures: Dry Chemical

Explosive: Non-explosive

Product Decomposition: . . . (Due to Fire or Explosion): Hydrogen gas, ZnO (under extreme external heat)

NFPA
Fire Diamond



Section 5

TOXICITY

Listed Carcinogen component: Chromium, Nickel Toxicology: See Sec. 2 (Chromium, Nickel) Route of Entry: Inhalation and Ingestion

Section 6

HEALTH EFFECTS AND FIRST AID

Inhalation: Dust may irritate mucous membranes and upper respiratory tract. Remove to fresh air and treat symptoms.

Ingestion: Rare in industry. Induce vomiting (do not induce vomiting or give a liquid to an unconscious person) and call a physician.

Eyes: Dust may irritate eyes. Wash with copious amounts of water for 15 minutes, if effects persist, call a physician.

Skin: Dust may irritate skin, causing forms of eczema. Wash with soap and water.

Long-Term Effects: Chronic overexposure may affect the following target organs or body systems—blood, digestive, respiratory, lungs, liver, kidneys and skin.

Comments: Special attention should be given to employees with anemia, restricted respiratory abilities, lung cancer, permanent kidney damage and metal-sensitive skin or skin lesions.

Section 7

PRECAUTIONS FOR SAFE HANDLING

Handling: Good personal and industrial hygiene should always be practiced. It is recommended that personal protective equipment be used by personnel who will come in contact with the material. The equipment should include eye protection, respirator and gloves.

Storage: Keep covered and avoid conditions where wind could cause dispersal. Do not eat, drink or smoke where material is handled to avoid inhalation or ingestion. Store in a dry area under cover from rain.

Spills: Cleaning procedures should not create excessive dust. Vacuum when possible. Package material and send to World Resources Company at above address.

Section 8

CONTROL MEASURES

Respiratory Protection: NIOSH-MSHA approved respirators as required.

Eye Protection: Safety Glasses recommended.

Other Protective Equipment: Coveralls are recommended, but not required.

Hand Protection: Gloves recommended.

Section 9

GENERATORS VERIFICATION

This MSDS is provided solely for informational purposes and no warranty or responsibility is extended even though reasonable precautions have been taken in the preparation of the data contained for this recyclable material. To the best of my knowledge this MSDS describes the recyclable material listed on the attached Manifest Number: 4004 Telephone: 623-5800 Date: 6-19-95

Company Name and Address: 628 Harbor ST SEATTLE WA 98134

Signature:

AZF-WRC 3/94

AKC-0018188

MATERIAL IDENTIFICATION

DOT SHIPPING NAME: Hazardous Waste Solid N.O.S. (F006)
DOT HAZARD CLASS: Class 9
UN OR NA NUMBER: NA 3077

1990
EMERGENCY
RESPONSE
GUIDE

DOT EMERGENCY RESPONSE GUIDE 31

POTENTIAL HAZARDS

FIRE OR EXPLOSION

Some of these material may burn, but none of them ignites readily.

HEALTH HAZARDS

Contact may cause burns to skin and eyes.

Fire may produce irritating or poisonous gases.

Runoff from fire control or dilution water may cause pollution.

EMERGENCY ACTION

Keep unnecessary people away.

Isolate hazard area and deny entry.

Self-contained breathing apparatus (SCBA) and structural firefighters, s protective clothing will provide limited protection.

CALL CHEMTREC AT 1-800-424-9300 FOR EMERGENCY ASSISTANCE.(Use Chemtrec Company Code "WORR") If water pollution occurs, notify the appropriate authorities.

FIRE

Small Fires: Dry chemical, CO2, Halon, water spray or standard foam.

Large fires: Water spray, fog or standard foam is recommended.

Move container from fire area if you can do it without risk.

Do not scatter spilled material with high-pressure water streams.

Dike fire control water for later disposal.

SPILL OR LEAK

Stop leak if you can do it without risk.

Small Dry Spills: With clean shovel place material into clean, dry container and cover, move containers from spill area.

Small spill: Take up with sand or other noncombustible absorbent material and place into containers for disposal.

Large Spills: Dike far ahead of liquid spill for later disposal.

Cover powder spill with plastic sheet or tarp to minimizing spreading.

FIRST AID

In case of contact with material, immediately flush eyes with running water for at least 15 minutes.

Wash skin with soap and water.

Remove and isolate contaminated clothing and shoes at the site.

NOTE: If this response guide is used as an attachment for shipping documents, enter shipping manifest number in block below.

WAD980738546

95004

(Shipping Manifest Number)

NOTICE

TO: World Resource Company
8112 West Sherman Street
Phoenix, Arizona 85043

From: Alaskan Copper Works
628 South Hanford Street
Seattle, Washington 98134

SUBJECT: Land Disposal Restriction Notice

Manifest Number: 95004

Date of Shipment: 6-19-95

This shipment of material, which is being provided for recycling, is subject to the land disposal restrictions of 40 CFR, Part 268, Subpart D or the prohibitions specified in 268.32 or RCRA 3004(d). The applicable Land Disposal Restriction Information is provided in accordance with 40 CFR 268.7 and is shown below:

EPA Material Number	Regulated Constituent	Subcategory	Treatability Group	Treatment Standards	
				CFR Reference	Prohibition Level
F006	N/A	N/A	Nonwastewater	40 CFR 268.41 40 CFR 268.43	---

By: Gerald A. Thompson
Alaskan Copper Environmental Assistant

Material Safety Data Sheet

F006 Recyclable Material (Filter Cake)

Recycler's Facility Name and Site Address:

World Resources Company
8113 West Sherman Street
Phoenix, Arizona 85043
Tele: 1-602-233-9166 Fax: 602-936-9164

Issued: 8/7/90
Revised: 9/15/93 - DLS

Call CHEMTREC only in the event of
emergencies during shipping that
involve a spill, leak, fire, or accident
(all calls are recorded)

For Emergencies During Shipping in
the US or Canada, Day or Night,
Call: CHEMTREC 800-424-9300
(Use Chemtrec Company Code "WRR")
For calls from other countries call:
202-483-7616 Collect

Section 1

Generic Name: Electroplating/Metal-Finishing Wastewater Treatment Sludge
Environmental Protection Agency (EPA) Waste Classification: F006
Chemical Family: Metallic (Hydroxide) Precipitates
Synonym: Non-ferrous Metal Hydroxide Filter Cake

PRODUCT - MATERIAL IDENTIFICATION

DOT Shipping Name: RQ, Hazardous waste, solid, n.o.s., (F006)
DOT Hazard Class: 9 Packaging Group III
DOT Identification Number: NA 3077
DOT Emergency Response Guide 31 Applies

Section 2

Ingredient:	CAS Number:
Copper Hydroxide	20427-59-2
Nickel Hydroxide	12054-48-7
Calcium Hydroxide	1305-62-0
Diatomaceous Earth	68855-54-9

Content %:

0-30
0-15
0-15
0-10

ACGIH-TLV

1.0 mg/m³ (Dust)
1.0 mg/m³ (Dust)
5.0 mg/m³ (Dust)
6.0 mg/m³ (Dust)

Toxicology: (rat, oral)

LD-50 1,000 mg/kg
LD-50 1,500 mg/kg
LD-50 7,340 mg/kg
LD-50 3,160 mg/kg

Section 3

HAZARDOUS INGREDIENTS

Description: Solid, Clay-like Clumps,
Gray/Green to Brown,
Water Content 30-80%

Specific Gravity: 1 to 1.4

Solubility: Insoluble in water

Density: 64 to 90 lbs/cu/ft

Incompatible Reactivity: None Known

Vapor Pressure: Insignificant

Stability: Avoid contact with acids

Polymerization: Will not occur

Boiling Point: Above 2600°C

Melting Point: Above 1800°C

pH: 7.0 to 10.0

Odor: Nil

Section 4

PHYSICAL AND REACTIVITY DATA

Flashpoint: Nonflammable

Special Firefighting Procedures: None

Product Decomposition: (Due to Fire or Explosion): None

Oxidation: Non-oxidizing

Explosive: Non-explosive

NFPA
Fire Diamond



Section 5

TOXICITY

Listed Carcinogen component: Nickel

Toxicology: See Sec. 2 (Nickel Hydroxide)

Route of Entry: Inhalation and Ingestion

Section 6

HEALTH EFFECTS AND FIRST AID

Inhalation: Dust may irritate mucous membranes and upper respiratory tract. Remove to fresh air and treat symptoms.

Ingestion: Rare in industry. Induce vomiting (do not induce vomiting or give a liquid to an unconscious person) and call a physician.

Eyes: Dust may irritate eyes. Wash with copious amounts of water for 15 minutes, if effects persist, call a physician.

Skin: Dust may irritate skin, causing forms of eczema. Wash with soap and water.

Long-Term Effects: Chronic overexposure may affect the following target organs or body systems—blood, digestive, respiratory, lungs, liver, kidneys and skin.

Comments: Special attention should be given to employees with anemia, restricted respiratory abilities, lung cancer, permanent kidney damage and metal-sensitive skin or skin lesions.

Section 7

PRECAUTIONS FOR SAFE HANDLING

Handling: Good personal and industrial hygiene should always be practiced. It is recommended that personal protective equipment be used by personnel who will come in contact with the material. The equipment should include eye protection, respirator and gloves.

Storage: Keep covered and avoid conditions where wind could cause dispersal. Do not eat, drink or smoke where material is handled to avoid inhalation or ingestion. Store in a dry area under cover from rain.

Spills: Cleaning procedures should not create excessive dust. Vacuum when possible. Package material and send to World Resources Company at above address.

Section 8

CONTROL MEASURES

Respiratory Protection: NIOSH-MSHA approved respirators as required.

Other Protective Equipment: Coveralls are recommended, but not required.

Eye Protection: Safety Glasses recommended.

Hand Protection: Gloves recommended.

Section 9

GENERATORS VERIFICATION

This MSDS is provided solely for informational purposes and no warranty or responsibility is extended even though reasonable precautions have been taken in the preparation of the data contained for this recyclable material. To the best of my knowledge this MSDS describes the recyclable material listed on the attached Manifest Number: Alaskan Copper Works 628 Telephone: (206) 623-5880 Date: 6-18-93

Company Name and Address:
Seattle WA 98134

Signature:

AZF-WRC 9/93